
INTEGRITY PRODUCTS


Insulation Spacer

To avoid the possibility of galvanic corrosion occurring the spacer band and the process pipe should NOT come into direct contact with each other.

At a minimum, the insulation spacers should be installed at the 2, 4, 8 and 10 o'clock positions. This frequency should increase with the pipe/insulation size to maintain a consistent air gap and ensure the spacer band does not come in direct contact with the process pipe.









install at minimum in the 2, 4, 8 & 10 o'clock positions



spacer band and process pipe should not come into direct contact

ONLINE VIDEO http://l.ead.me/bauPyZ



